


△ = 1/8" DIA EQUAL PRESSURE HOLE
(CENTER LINE OF TOP HORIZONTAL)

○ = 1/4" DIA WEEP HOLE
(APPROX 3" FROM EDGE)


□ = FACE MOUNTED WEEP
(APPROX 3" FROM EDGE)

⊞ = WEEP OPTIONS: HOLE TO
WEEP INTO SUBSILL, OR FACE
MOUNTED WEEP IF NO SUBSILL
(APPROX 3" FROM EDGE)


DRY GLAZED VENTS WEEP
INTO STANDARD WEEPING
SYSTEM OF OUTSIDE FRAME




X51




X55




X57




X58




X52




X53




X54



X59



X96



X9A


△ = 1/8" DIA EQUAL PRESSURE HOLE
(CENTER LINE OF TOP HORIZONTAL)

○ = 1/4" DIA WEEP HOLE
(APPROX 3" FROM EDGE)


□ = FACE MOUNTED WEEP
(APPROX 3" FROM EDGE)

⊞ = WEEP OPTIONS: HOLE TO
WEEP INTO SUBSILL, OR FACE
MOUNTED WEEP IF NO SUBSILL
(APPROX 3" FROM EDGE)


DRY GLAZED VENTS WEEP
INTO STANDARD WEEPING
SYSTEM OF OUTSIDE FRAME




X0E




X0D




X5A




X0B




X0A







X56




X5B




X5C






1



3

2



OS OPERATOR HANDLE

4

