


△ = 1/8" DIA EQUAL PRESSURE HOLE
 (CENTER LINE OF TOP HORIZONTAL)


○ = 1/4" DIA WEEP HOLE
 (APPROX 3" FROM EDGE)

□ = FACE MOUNTED WEEP
 (APPROX 3" FROM EDGE)


⊙ = WEEP OPTIONS: HOLE TO
 WEEP INTO SUBSILL, OR FACE
 MOUNTED WEEP IF NO SUBSILL
 (APPROX 3" FROM EDGE)




X01




X09




X08




X04




X02




X05




X06



X03



X07




X76

△ = 1/8" DIA EQUAL PRESSURE HOLE
 (CENTER LINE OF TOP HORIZONTAL)


○ = 1/4" DIA WEEP HOLE
 (APPROX 3" FROM EDGE)

□ = FACE MOUNTED WEEP
 (APPROX 3" FROM EDGE)


⊖ = WEEP OPTIONS: HOLE TO
 WEEP INTO SUBSILL, OR FACE
 MOUNTED WEEP IF NO SUBSILL
 (APPROX 3" FROM EDGE)




X78




X84




X77




X83




X73




X34




X01




X09




X08




X04




X02




X05




X06




X03




X07




X76




X78




X84




X77




X83




X73



X34



1




4

NO SEAL GASKET
FOR EQUAL
PRESSURIZATION

OS OPERATOR HANDLE

2



3

